



Another ECDIS induced accident: After all these years, why can't we get it right?

T. Porathe, E. S. Petersen, M. Lützhöft

HVL, Western Norway University of Applied Sciences, Norway

The ErgoShip conference, Esbjerg, Denmark, 2-3 November 2023



UK participants in Project OCEAN are supported by UKRI grant numbers
10038659 (Lloyds Register) and 10052942 (The Nautical Institute).






ACCIDENT REPORT

Report on the investigation of
the grounding of the general cargo vessel
Kaami
on Sgeir Graidach, the Little Minch, on
23 March 2020

MAIB
MARINE ACCIDENT INVESTIGATION BRANCH






The Little Minch

Slite

ACCIDENT REPORT

Report on the investigation of
the grounding of the general cargo vessel
Kaami
on Sgeir Graidach, the Little Minch, on
23 March 2020

MAIB
MARINE ACCIDENT INVESTIGATION BRANCH



SERIOUS MARINE CASUALTY








Figure 15: Different routes due to weather routing. Photo of onboard ECDIS. Courtesy of MAIB








Figure 12: Photo of Kaami's ECDIS display showing route in comparison to the missing cell (indicated by vertical bars) which covered the IMO recommended route to the north of the Isle of Skye. Courtesy of MAIB.







Figure 4: Aerial view from coastguard helicopter's video showing the general cargo vessel *Kaami* aground on *Sgeir Graidach*. Courtesy of MAIB.



The question we may ask is: How could a fully equipped, modern ship, with a properly manned bridge, plan a track away from the IMO recommended route and run aground in good visibility on a charted rock?

Is this yet another ECDIS induced accident?

So, how come we after all these years, still can't get it right?

And is there something the ECDIS designers can do about it?

The Electronic Chart and Display Information System, ECDIS




JRC JAN 2000 ECDIS



Kaami's bridge. Photo courtesy of MAIB.


James Reason's Swiss Cheese Model





SAFETY BARRIERS

ECDIS






SAFETY BARRIERS

ECDIS

Familiarisation



STCW, regulation I/14, ISM Code section 6.3




STCW

The International Convention on Standards of Training, Certification and Watchkeeping for Seafarers, 1978

STCW, 2010, Part 2: Voyage Planning


“The intended voyage shall be **planned in advance** taking into consideration all pertinent information and any course laid down **shall be checked** before the voyage commences.”





Kaami's route passing over shoal waters after WP 19. Photo from the ship's ECDIS. Courtesy MAIB.

Figure 16: Route 37 crossing the safety contour before the Kattegat waypoint. ECDIS route showing an area to the north of the Danish coast, as the route passed from the Skagerrak into the Kattegat, where the safety contour was crossed Courtesy of MAIB.






SAFETY BARRIERS

ECDIS

Familiarisation

Voyage Plan



STCW, regulation I/14, ISM Code section 6.3

STCW, IMO A.893(21)




SAFETY BARRIERS

ECDIS

Familiarisation

Voyage Plan

Voyage plan second check signed by master





Second check

SOLAS Annex 23 (voyage planning) states the following inter alia:

‘Masters, skippers and watchkeepers should therefore adhere to the IMO Guidelines taking the following measures to ensure that they appreciate and reduce the risks to which they are exposed: ...

b) ensure that there is a systematic bridge organisation that provides for:

- - -

iii) cross checking of individual human decisions so that errors can be detected and corrected as early as possible’.




SAFETY BARRIERS

ECDIS


Familiarisation

Voyage Plan

Voyage plan second check signed by master



Kaami's draught 5.4 m (aft) + Under-Keel Clearance (UKC)



Depth Alert

Shallow Contour	5 m
Safety Contour	5 m
Safety Depth	7 m
Deep Contour	25 m

Four shades

Shallow Pattern

Shallow water dangers

Chart Graphics Performance

- Fast
- Hi Quality

C-MAP Ed.3 Database

OK Cancel Apply



SAFETY BARRIERS

ECDIS

Familiarisation

Voyage Plan

Voyage plan second check signed by master

Safety Contour correctly set







Figure 14: Automatically generated alarm for crossing a safety contour. Courtesy of MAIB



Figure 8: Voyage planning screen showing XTD and safety check. Voyage planning display screen with cross track limit and automatic safety check data highlighted. Courtesy of MAIB





SAFETY BARRIERS

ECDIS


Familiarisation

Voyage Plan

Voyage plan second check signed by master

Safety Contour correctly set

ECDIS Route Safety Check






Figure 12: Photo of *Kaami's* ECDIS display showing route in comparison to the missing cell (indicated by vertical bars) which covered the IMO recommended route to the north of the Isle of Skye. Courtesy of MAIB.



SAFETY BARRIERS

ECDIS

Familiarisation

Voyage Plan


Voyage plan second check signed by master

Safety Contour correctly set

ECDIS Route Safety Check

Inappropriate Scales used

Missing ENC cell









Figure 9: Look ahead options on Kaami's JRC JAN 2000 ECDIS. Kaami's ECDIS screen showing boxes for activating look ahead were unchecked. Courtesy of MAIB.

Limit

<input type="checkbox"/>	Difference between POSN1 and POSN2	1.000 NM
<input type="checkbox"/>	Shift of POSN1	1.000 NM
<input type="checkbox"/>	Course difference(Off Course)	015.0 °
<input type="checkbox"/>	Early Course Change Indication	1.0 min
<input type="checkbox"/>	End of track(Arrived LAST WPT)	1.0 min
<input type="checkbox"/>	Timer	Alert occurs at 05:40 (LMT)

<input type="checkbox"/>	Vector	Length	3.0 min
<input type="checkbox"/>		Width	250.0 m
<input type="checkbox"/>	Sector	Radius	1.0 min
<input type="checkbox"/>		Width	045.0 °

Area

- Traffic separation zone.
- Traffic crossing.
- Traffic roundabout.
- Traffic precautionary.
- Two way traffic.
- Deeper water route.
- Recommended traffic lane.

Boxes must be checked to activate look ahead



Figure 10: Alert buzzer settings all set to zero





SAFETY BARRIERS

ECDIS

Familiarisation

Voyage Plan

Voyage plan second check signed by master

Safety Contour correctly set

ECDIS Route Safety Check

Inappropriate Scales used

Missing ENC cell

Look Ahead function inactivated

The alarm audio buzzers inactivated

Hazards



STCW, regulation I/14, ISM Code section 6.3

STCW, IMO A.893(21)

IMO A.893(21)

IMO A.893(21),

IMO, MSC.232(82)

IMO, MSC.232(82)

IMO, MSC.232(82)

IMO, MSC.232(82)

IMO, MSC.232(82)



Why did the navigators onboard disable all the helpful features design into the system to help them?

Where they even aware of that the features were inactivated or that they had missed doing some action?

Fatigue?

Complicated technology. Unintuitive design?
(Low learnability, low usability)



And what can we do about it?



UK participants in Project OCEAN are supported by UKRI grant numbers 10038659 (Lloyds Register) and 10052942 (The Nautical Institute).





Potential solutions (ranked No to High policing)

1. **Nudging for better design.** Improved usability through Human-Centred Design. S-mode.



Potential solutions (ranked No to High policing)

1. **Nudging for better design.** Improved usability through Human-Centred Design. S-mode.
2. **Regulations.** Recommendations and guidelines should be firmer, e.g., Ships **MUST** sail with safety checked routes, activated alarms and look ahead functions.



Potential solutions (ranked No to High policing)

1. **Keep nudging for better design.** Improved usability through Human-Centred Design. S-mode.
2. **Regulations.** Recommendations and guidelines should be firmer, e.g., Ships **MUST** sail with safety checked routes, activated alarms and look ahead functions.
3. **Prevent “dangerous” settings**, e.g., the ability to turn off alarms, buzzers and warnings, inactivate look-ahead functions and automatic route checks. Remove the possibility to set faulty Safety Depth and Safety Contour. (How? Automatic draught gauges? Set by harbour authorities?)



Potential solutions (ranked No to High policing)

1. **Keep nudging for better design.** Improved usability through Human-Centred Design. S-mode.
2. **Regulations.** Recommendations and guidelines should be firmer, e.g., Ships **MUST** sail with safety checked routes, activated alarms and look ahead functions.
3. **Prevent “dangerous” settings**, e.g., the ability to turn off alarms, buzzers and warnings, inactivate look-ahead functions and automatic route checks. Remove the possibility to set faulty Safety Depth and Safety Contour. (How? Automatic draught gauges? Set by harbour authorities?)
4. **Clears visual indicators when ECDIS’ settings are not complete.**




Potential solutions (ranked No to High policing)

1. **Keep nudging for better design.** Improved usability through Human-Centred Design. S-mode.
2. **Regulations.** Recommendations and guidelines should be firmer, e.g., Ships **MUST** sail with safety checked routes, activated alarms and look ahead functions.
3. **Prevent “dangerous” settings**, e.g., the ability to turn off alarms, buzzers and warnings, inactivate look-ahead functions and automatic route checks. Remove the possibility to set faulty Safety Depth and Safety Contour. (How? Automatic draught gauges? Set by harbour authorities?)
4. **Clears visual indicators when ECDIS’ settings are not complete.**
5. **Lock down ECDIS if all mandatory settings is not OK.** Is this too much?



Potential solutions (ranked No to High policing)

1. **Keep nudging for better design.** Improved usability through Human-Centred Design. S-mode.
2. **Regulations.** Recommendations and guidelines should be firmer, e.g., Ships **MUST** sail with safety checked routes, activated alarms and look ahead functions.
3. **Prevent “dangerous” settings**, e.g., the ability to turn off alarms, buzzers and warnings, inactivate look-ahead functions and automatic route checks. Remove the possibility to set faulty Safety Depth and Safety Contour. (How? Automatic draught gauges? Set by harbour authorities?)
4. **Clears visual indicators when ECDIS’ settings are not complete.**
5. **Lock down ECDIS if all mandatory settings is not OK.** Is this too much?
6. **Social control.** Flag ships AIS target as “unreliable” through an AIS message, e.g., “Voyage plan not Safety Checked.”





Potential solutions (ranked No to High policing)

1. **Keep nudging for better design.** Improved usability through Human-Centred Design. S-mode.
2. **Regulations.** Recommendations and guidelines should be firmer, e.g., Ships **MUST** sail with safety checked routes, activated alarms and look ahead functions.
3. **Prevent “dangerous” settings**, e.g., the ability to turn off alarms, buzzers and warnings, inactivate look-ahead functions and automatic route checks. Remove the possibility to set faulty Safety Depth and Safety Contour. (How? Automatic draught gauges? Set by harbour authorities?)
4. **Clears visual indicators when ECDIS’ settings are not complete.**
5. **Lock down ECDIS if all mandatory settings is not OK.** Is this too much?
6. **Social control.** Flag ships AIS target as “unreliable” through an AIS message, e.g., “Voyage plan not Safety Checked.”
7. **Automatic message to VTS** and Coast Guard Centres if mandatory ECDIS settings are not followed.

Thank you for listening

Corresponding author: thomas.porathe@ntnu.no